## KING COUT Y INTERNATIONAL AIRPORT INC. THE REPORT

INCIDENT: FUEL SPILL	DATE OCCURRED 6-25-93	DATE REPORTED
	TIME OCCURRED 1900	TIME REPORTED
LOCATION(S) OF OCCURRENCE:	11 TAXIWAY	
REPORTED BY:	PHONE NO(S):	
TOWER	THORE MOOR	
to the area from a previous the first at the IFR ho	a pilot report of an "Oil Spill" at A ious ALERT and observed two stains, a ld line; the second about 35 ft east e result of previously unreported Jet ashed down with water.	approximately 18" in diameter, of the east edge of the runway.
officers: LBCL Action:	LEB CLD CLD SHD PEM	GO SO JW W SO